ROCKY FLATS PLANT **EMD OPERATING** PROCEDURES MANUAL Manual No.: Procedure No.:

Page:

5-21000-OPS-GT Table of Contents, Rev 7

Effective Date:

11/15/91

Organization:

**Environmental Management** 

## THIS IS ONE VOLUME OF A SIX VOLUME SET WHICH INCLUDES:

VOLUME I: FIELD OPERATIONS (FO) **VOLUME II: GROUNDWATER (GW)** 

VOLUME III: GEOTECHNICAL (GT) VOLUME IV: SURFACE WATER CONTROLLED DO

LUME V: ECOLOG. LEURG - ROCKY FLATS PLANT VOLUME VI: AIR (AP) ENTRONMENTAL MANAGEMENT DEPARTMENT

TABLE OF CONTENTS FOR VOLUME III: GEOTECHNICAL This is a RED Stamp

This is a

New Proc. No.	Old Proc. No.	<u>Title</u>	Rev. <u>No.</u>	Effective ** Date
GT.01	3.1	Logging Alluvial and Bedrock Material	1	8/30/91
DCN 91.01	•	Recording lithologic descriptions and securing core boxes	1	11/15/91
GT.02	3.2	Drilling and Sampling Using Hollow Stem Auger Techniques	1	8/30/91
DCN 91.01		Unconsolidated core samples need not peeled before sampling	be	10/29/91
DCN 91.02		Correction of well location for low Alluvial thickness		11/6/91
DCN 91.03		Ten foot long core barrels	1	11/15/91
GT.03	3.3	Isolating Bedrock From the Alluvium with Grouted Surface Casing	1 1	8/30/91
DCN 91.01		Change in criteria for cement grouting	1	10/02/91
DCN 91.02		Grout procedure clarification	1	10/28/91

A-SW-001094

**ADMIN RECORD** 

ROCKY FLATS PLANT EMD OPERATING PROCEDURES MANUAL Manual No.: Procedure No.: Page:

Page: Effective Date: Organization: 5-21000-OPS-GT Table of Contents, Rev 7

2 of 3 11/15/91

**Environmental Management** 

New Proc. No.	Old Proc. No.	Title	Rev. <u>No.</u>	Effective Date
GT.04	3.4	Rotary Drilling and Rock Coring	1	8/30/91
DCN 91.01		Core barrel decontamination	1	10/22/91
DCN 91.02		Clarification of measuring tape decontamination requirements	1	10/29/91
GT.05	3.5	Plugging and Abandonment of Boreholes	1	8/30/91
DCN 91.01	:	Surface casing classification	1	10/22/91
GT.06	3.6	Monitoring Wells and Piezometer Installation	1	8/30/91
DCN 91.01		Industry Standard is 1 foot into Bedrock	1	10/15/91
DCN 91.02		For the Sitewide Program, Claystone Smearing does not seem to be a problem	 1	10/15/91
DCN 91.03	•	Superseded by DCN 91.06	<b>.1</b>	11/08/91
DCN 91.04		Low Alluvial thickness wells	1	11/06/91
DCN 91.05		Superseded by DCN 91.08	1	11/06/91
DCN 91.06		Change in filter pack guidance	1	11/08/91
DCN 91.07	,	Decontamination for site-wide geological characterization	• <b>1</b> • • • • • • • • • • • • • • • • • • •	11/15/91
DCN 91.08	The second se	Figure replacement (GT.6-1)	1	11/15/91
GT.07	3.7	Logging and Sampling of Test Pits and Trenches	1	8/30/91
GT.08	3.8	Surface Soil Sampling	1	8/30/91
GT.09	3.9	Soil Gas Sampling and Field Analysis	1	8/30/91
GT.10	3.10	Borehole Clearing	1	8/30/91
GT.11	3.11	Plugging and Abandonment of Wells	1	8/30/91



ROCKY FLATS PLANT EMD OPERATING PROCEDURES MANUAL			Manual No.: Procedure No.: Page: Effective Date:	5-21000-OPS-GT Table of Contents, Rev 7 3 of 3 11/15/91		
			Organization:	Environmental		
	•	. which is a second second				
GT.15	3.15	Geophysical Boreh	ole Logging	1	8/30/91	
DCN 91.01		No Hole will be left of the day	Unlogged at the end	1	10/15/91	
GT.17	3.17	Land Surveying		1	8/30/91	
GT.18	3.18	Surface Geophysica	al Surveys	* . <b>1</b>	8/30/91	
GT.19	3.19	Field Gas Chromato	graphs	1	8/30/91	
GT.20	3.20	Procedures for Soil Sampling and Samp		1	8/30/91	

## ENVIRONMENTAL MANAGEMENT DOCUMENT CHANGE NOTICE (DCN)

Procedure Number 5-21000-OPS-GT.2, Rev. 1

Page 1 of 1

Title Drilling	and Sam	pling Using H	ollow-Stem Au	ger Techniqu	Da Jes 1	te 1-14-91	DCN Num 5-21000-0	ber DPS-GT.2- 1.03
Expires	2-15-6	72	Pr	ocedure Rev	ision Required	X Yes No		
Scope U	mitation	none						14 a 3
					ENVIROR	Walter CORY		
item Number	Page	Step or Paragraph		(Use D		hanges ON SMEET for Add		ce)
1	4 of 14	paragraph 2	obtain up to 1 sampling will	10-foot-long of be conducted	cores in a 10-foot-i	ntinuous coring te ong sample barrei 2 feet to enhance iling Plan (FSP)."	; however, a	st AFP, 💛
		on for Change barrels are co	•		-	nding items Above	)	
							٠	
Concur	ence	Organizatio	n Req	Date	Concurrence	Organization	Req	Date
Trees	ninin	QAPM	Х	11/14/61	al Pumo	User	×	4/14/91
#/ _ \ /\	muara	EOM	X	ग्रीभीवा				
Approval to CN Form 001	of Flespor	sible Manage	Pate /4 /W	291	Is Posting Reqd?		Date?	Date Posted